

Material Safety Data Sheet

DATE OF PREPARATION: 1-27-99

Goff's Enterprises, Inc.
1228 Hickory Street
Pewaukee, WI 53072
days per week

For Chemical Emergency
Call: 1-800-255-3924
24 hours per day/7

SECTION I – FILTER MATERIAL IDENTIFICATION

Material Name: Non-woven fabric, fibers bonded or coated with polymers.

Fiber types: synthetic, binder types: hulogenated & acrylic polymers.

Product codes: 115002 (FP-50), 115003 (FP-100), 115053 (FP-75), 115060 (PST-100), 115067 (M-05ST), 115709 (DFN-100), 165009 (R-1), 215011 (FP-200), 215012, 215014 (M-10ST), 215015 (M-90), 215017

SECTION II – HAZARDOUS INGREDIENTS

Non-hazardous in normal use.

SECTION III – PHYSICAL DATA

Appearance & Odor: Soft, fibrous structures. No distinctive odor.

Density in LBS. Per Cubic Feet: Varies

Melting Point in Degrees C.: Binder softens with heat; fiber melts over 230° C.

Evaporations Rate: Negligible at ambient temperatures.

SECTION IV – FIRE AND EXPLOSION DATA

Flash point does not apply to these fibrous materials.

Burning Characteristics: Flame-retarded, self extinguishing.

Explosive limits do not apply.

Extinguishing media: Water spray, dry chemical, or carbon dioxide.

Fire fighting procedures: Wear positive pressure self-contained breathing apparatus and protective clothing.

SECTION V – REACTIVITY DATA AND PHYSICAL HAZARDS

These materials are stable during normal use.

Conditions to avoid: Avoid exposures to temperatures over 121°C (250°F).

Vapor smoke could be liberated over this temperature.

Hazardous decomposition procedure: Carbon monoxide and dioxide,
hydrogen chloride,
small quantities of aliphatic and aromatic hydrocarbons, antimony oxide and/or
oxychloride.

SECTION VI – HEALTH HAZARD INFORMATION

Effect of exposure: Acute effects may occur in rare instances to produce a mild
Skin and eye irritation which is readily reversible.

No known chronic effects.

Not known to be sensitizer.

SECTION VII – DISPOSAL PROCEDURES

Waste disposal method: Dispose of in accordance with current federal, state, and local regulations.

SECTION VIII – SAFE HANDLING AND USE INFORMATION

Respiratory Protection: None required.

Ventilation: Use good general ventilation. If product is hotwire cut, provide local exhaust to remove fumes.

Protective Gloves: Impervious.

Eye Protection: Safety glasses should be worn in any type of industrial operation.

SECTION IX – SPECIAL PRECAUTIONS

None.

This information contained herein is furnished without warranty of any kind. Users should consider these data as a supplement to other information gathered by them and must make independent determinations or suitability and completeness of information from all sources to assure proper use and disposal of these materials and the health and safety of employees and customers.